



P23985.A20

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s): Y. S. NAM et al. <u>Certificate of Corrections Branch</u>

Patent No. : 6,865,899 Issued: March 15, 2005

Appl. No. : 10/621,656 Filed: July 18, 2003

For : REGRIGERATOR AND METHOD OF CONTROLLING THE SAME

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Certificate SEP 2 0 2005 of Correction

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following errors appearing in the printed patent, which are the fault of the U.S. Patent and Trademark Office, as per the attached Certificate of Correction. Since these errors are the fault of the USPTO, no fee is due.

At column 22, line 10 (claim 1, line 16) of the printed patent, after "freezing" delete ", ". This appeared correctly on page 61, line 8 of the Specification filed July 18, 2003.

At column 22, line 22 (claim 1, line 28) of the printed patent, "load-in" should be ---load in---. This appeared correctly on page 61, line 19 of the Specification filed July 18, 2003.

Therefore, it is respectfully requested that a Certificate of Correction issue in the aboveidentified patent as follows:



P23985.A20

At column 22, line 10 (claim 1, line 16) of the printed patent, after "freezing" delete ", ".

At column 22, line 22 (claim 1, line 28) of the printed patent, "load-in" should be ---load in---.

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted, Y. S. NAM et al.

Bruce H. Bernstein Reg. No. 29,027 _

William Pieprz Reg. No. 33,630

September 15, 2005 GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191 (703) 716-1191

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,,865,899

DATED

: March 15, 2005

INVENTOR(S): Y. S. NAM et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 22, line 10 (claim 1, line 16) of the printed patent, after "freezing" delete ", ".

At column 22, line 22 (claim 1, line 28) of the printed patent, "load-in" should be ---load in---.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,,865,899

GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commence, P.O. Box 1450, Alexandria, VA 22313-1450, DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.